

## Gowning Procedures

1. Put on *bouffant cap* and *face cover AND FACE MASK*



2. Jump in the *coverall suit*



- Put on *shoe-covers* (if necessary- most of our new coverall suits come with the boots)



- For extra protection during microfabrication, wear always *nitrile gloves*, and *over sleeves*, *safety goggles* and *Nitrile industrial chemical gloves* if necessary before starting the process.



5. For executing acid or corrosive chemical process, *face shield, apron and extra over sleeves* are required.

