

Gowning Procedures

1. Put on *bouffant cap* and *face cover*



2. Jump in the *coverall suit*



3. Put on *shoe-covers* (if necessary- most of our new coverall suits come with the boots)



4. For extra protection during microfabrication, *safety goggles*, *nitrile gloves* and *oversleeves* are necessary before starting the process.



5. For executing acid or corrosive chemical process, *face shield, apron and extra oversleeves* are required.

